Thursday, 14/08/2008 11:50:50 AM

User:

Linda Lacelle

Process Sheet -

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** : 41245 : 12576

P.O. Number

This Issue : 14/08/2008

: NC

Prsht Rev.

First Issue **Previous Run** : // : 41038

S.O. No. :

Type

: LARGE FAB ASSY

Part Number

Drawing Name

Drawing Number

: D3562041 : D3562 REV E

: STEP WELDMENT

Project Number

: N/A

Drawing Revision Material

: E

Due Date

: 21/08/2008

Qty:

2 Um:

Each

Written By

Checked & Approved By

Comment

: Est Rev:A

Est rev B Est Rev:C **E**CN 987 ECN1048 07.10.09 EC verified by: DD

New Issue 06-11-09 JLM

07-12-18 DD verified by:ec

08-07-28 add chemical conversion coat DD

Est Rev:D verified by:EC

Additional Product

Job Number:



Seq. #:

∯.vo> •€.v°°

Machine Or Operation:

Description:

1.0

D2622120C

Qty

Step Extrusion

Ø

Comment: Qty.:

Part#

1.0000 Each(s)/Unit Total: Description

Batch:

D2622-120C

Extrusion

39316

2.0000 Each(s)

Check Material for any Dents or Defects

2.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2622 extrusion as per Dwg D3562

2-Deburr and bevel ends for welding

3.0

QC5

INSPECT WORK TO CURRENT STE



Comment: INSPECT WORK TO CURRENT STEP

4.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1



Dart Aerospace Ltd

W/O:		WORK ORDER	CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No:		1,3		_ PAR #: ˌ		NCR: Yes No DQA:	Date:
			The Heat, 1				
	:				· ·	QA: N/C Closed:	Date:

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC		Corrective Action Section	В	Verification	A	Approval QC Inspector
	STEP	Section A	Initial : Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	
						i.		
			*					0.00 (5.00 (4.00 (4.00)
			,				\$	

NOTE: Date & initialial entries

Jan 2 6:02

Date: Thursday; 14/08/2008 11:50:50 AM User: Linda Lacelle **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 41245 Part Number: D3562041 Job Number: Seq. #: Description: **Machine Or Operation:** INSPECT POWDER COAT/CHEMICAL CONVERSION 5.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 6.0 D3560041 Arm Weldment Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) ARM WELDMENT D3560043 7.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Blind Rivet 8.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 64.0000 Each(s) Blind Rivet batch: SMALL & MEDIUM FAB RESOURCE 1 9.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- Transfer drill Rivet holes as per dwg D3562. 2-Touch-up rivet holes with alodine as per dwg d3562 3-Rivet legs using Magnabond as per dwg D3562. ******Ensure to wipe off any exess magnobond ****** Batch: m/6695 A/R Magnabond 6398 10.0 QC5 NSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP

Dart Aerospace Ltd 4

W/O:		WORK ORDER (CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,	<u>.</u>	•		. Pro
Part No:		DAP # Fault Catagony	NCP: Voc	No DO	Α.	Data	

QA: N/C Closed: ____ Date: ____

NCR:	4.30		WORK ORD	ER NON-CONFORMANC	E (NCR)			
!		Description of NC		Corrective Action Section B		Varification	A	A
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
	10							
							i i	
	ıķ		- N				i	
1	Ī						;	
				\h.			ļ	
	7 (A)						:	
							İ	
:							:	

Date: Thursday, 14/08/2008 11:50:50 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 41245 Part Number: D3562041 Job Number: Seq. #: Description: Machine Or Operation: 11.0 D2734 Step End Plate Comment: Qty.: 4.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: Description Batch **Qty Part Number** End Cap 339 179 2 D2734 12.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld end caps as per Dwg D3562& QSI 004. Inspect for foreign objects as per QSI 024. Aluminum Rod 1108031 2-Grind end cap welds flush as per Dwg D3562 13.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 14.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 15.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4/ POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** PS 30,80 /K FINISH TIME:

Dart Ae	rospace	Ltd							
W/O:			WC	ORK ORDER CHANGE	ES			1	
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•				i	
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	\:	Date:	
			•	*	QA: N	/C Closed	l:	_ Date: _	
NCR:		V	VORK ORDI	ER NON-CONFORMA	NCE (NCF	R)		·····	
		Description of NC		Corrective Action Section	n B	Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
			,					!	

_		100		11 11 11 11	
1120	$\Lambda \sim$	FAC	2	^^	18 4 ~ .
Dart	ME	103	ua		Latu.
				military of 3	

W /O:		WORK ORDER	CHANGES		1
DATE	STEP	PROCEDURE CHANGE	By Date	Qty	Approval Chief Eng / Prod Mgr Approva QC Inspecto
					. ;
Part No:		PAR #: Fault Category:	NCR: Yes No DO	QA:	Date:

QA: N/C Closed: ____ Date:

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section E	3	Verification	Annaval	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	
						,		
: 								

Date: Thursday, 14/08/2008 11:50:50 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 41245 Part Number: D3562041 Job Number: Seq. #: Description: Machine Or Operation: HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D3562 and QSI 005 4.4 Batch: 1/108496 18.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION POWDER COAT/CHEMICAL CONVERSION Comment: INSPEC **PACKAGING** 19.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE Pick Assembly Kit 20.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CHAI	WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							·			
		•								
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:				

QA: N/C Closed: ____ Date: ___

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	_	Description of NC		Corrective Action Section B		Verification	A	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng				
							:				
							t.				
							÷				
							į				
•		. `									

